Appln. No. 10/564,039 Preliminary Amd. dated October 11, 2006

REMARKS

An error has been discovered in the text of the above-identified application, and this error has been corrected above.

Reference numeral 36 relates to a driving circuit (page 55, lines 4 and 5, and line 18). It is element 32 which relates to a voltage-elevating circuit (page 55, line 3); also see Fig. 3. Accordingly, no new matter is introduced by the correction made above.

Respectfully submitted,

BROWDY AND NEIMARK, P.L.L.C. Attorneys for Applicant

Bv

Sheridan Neimark Registration No. 20,520

SN:jec

Telephone No.: (202) 628-5197 Facsimile No.: (202) 737-3528

G:\BN\S\SUMA\Fujiwara4\Pto\2006-10-11 PREL AMD.doc